

Anstro Mfg Inc.

238 Wolcott Rd.
Wolcott Ct. 06716
203-879-1423

Hydraulic Brake Group

Bulletin

Bulletin Number 124
Jan 26, 2006

FMSI No: D1194(8312)

Application:

2007: Chevrolet Tahoe (Rear)
2007: GMC Yukon (Rear)

Anstro Sales Information:

Phone: 203-879-1423
Michele Pelletier in Sales
Email: michele.pelletier@anstroinc.com
Fax: 203-879-2823




Plate: D1194-OUTER






Plate: D1194-INNER



Shim: A-4996-CL



Sensor: A-458-S



Caliper Hardware (Caliper Abutment Clip)
Anstro Part Number: A-8250-S, A-8250-SR
IBI Part Number: 23638, 23638Q

Visit our Web Site <http://www.anstroinc.com>

Caliper Hardware can be purchased through IBI

Contact: Jean Sroufe 419-993-8140

Some Original Equipment parts shown for reference. Anstro aftermarket product designs may vary.