

Hydraulic Brake Group

Anstro Mfg Inc.

Bulletin

Call For Sales/Customer Service

Bulletin Number 175
Sept 5, 2008

Anstro Mfg: 203-879-1423
Gunn Metal: 519-836-6672
International Brake: 419-993-8140


FMSI No. :D1378 (8396)

Application:

2009 : Honda Pilot (Front)



Plate: D1378-IL Gunn Metal
Plate: D1378-IR
Plate: D1378-O



Shim: A-5150-CLVT Anstro Mfg.



Caliper Hardware (Pad Spreader)
22022 (IBI Part Number)



Caliper Hardware (Abutment Clip)
Anstro Part Number: A-8280 (23989)
A-8281-S, (23990)
(IBI Part Number)



Sensor: A-499-S Anstro

Visit our Web Sites <http://www.anstroinc.com>
<http://www.ibilima.com>

Some Original Equipment parts shown for reference. Aftermarket product designs may vary.