

Hydraulic Brake Group

Anstro Mfg Inc.

Bulletin

Call For Sales/Customer Service

Bulletin Number 210
Sept 22, 2009

Anstro Mfg: 203-879-1423
Gunn Metal: 519-836-6672
International Brake: 419-993-8140

FMSI No. :D1421(8536)


Application:
2010 Buick Lacrosse (Front)



Plate: D1421-Outer Anstro Mfg.



Plate: D1421-Inner Anstro Mfg.



Shim: A-5250-CLVT Inner & Outer
Anstro Mfg.



Sensor: A-537-S Anstro Mfg.



Abutment Clip: A-8348-S Anstro Mfg.
24320 IBI

Visit our Web Sites <http://www.anstroinc.com>
<http://www.ibilima.com>

Some Original Equipment parts shown for reference. Anstro aftermarket product designs may vary.