

# Anstro Mfg Inc.

238 Wolcott Rd.  
Wolcott Ct. 06716  
203-879-1423

Hydraulic Brake Group

# Bulletin

Bulletin Number 120  
Nov 29, 2005

**FMSI No. :D1109 (8214)**

**Application:**

2006: Ford Explorer (Rear)

**Anstro Sales Information:**

Phone: 203-879-1423

Michele Pelletier in Sales

Email: michele.pelletier@anstroinc.com

Fax: 203-879-2823




**Plates:** D1109-LORI  
USE D981-OLM



**Caliper Hardware : (Rail Clip)**

Anstro Part Numbers: A-8113-S, A-8113-SR

IBI Part Numbers: 22581, 22581Q



**Plates:** D1109-ROLI  
USE D981-ORM



**Hardware:** A-193-S

**Hardware:** A-194-S



**Shim:** A-4188-CL



**Hardware:** A-387-LH, A-388-RH

Visit our Web Site <http://www.anstroinc.com>

**Caliper Hardware can be purchased through IBI**

**Contact: Jean Sroufe 419-993-8140**

*Some Original Equipment parts shown for reference. Anstro aftermarket product designs may vary.*