

# Hydraulic Brake Group

Anstro Mfg Inc.

# Bulletin

Call For Sales/Customer Service

Anstro Mfg: 203-879-1423

Gunn Metal: 519-836-6672

International Brake: 419-993-8140

Bulletin Number 151  
Sept 28, 2007


**FMSI No. :D1325 (8437)**

**Application:**

2008: Toyota Highlander (Rear)



Plate: D1325 Gunn Metal



Shim: A-4268-CLSD Anstro Mfg.



Shim: A-5205-CLVT Anstro Mfg.




Caliper Hardware (Abutment Clip)

Anstro Part Number: A-8300-S, (24074)  
(IBI Part Number)



Sensor: A-510-S Anstro Mfg.



Caliper Hardware (Abutment Clip)

Anstro Part Number: A-8301-S, (24075)  
(IBI Part Number)

Visit our Web Sites <http://www.anstroinc.com>  
<http://www.ibilima.com>

*Some Original Equipment parts shown for reference. Aftermarket product designs may vary.*