

Hydraulic Brake Group

Anstro Mfg Inc.

Bulletin

Call For Sales/Customer Service

Bulletin Number 170
April 24, 2008

Anstro Mfg: 203-879-1423
Gunn Metal: 519-836-6672
International Brake: 419-993-8140

FMSI No. :D1351 (8461)

Application:

2007-06: Chevrolet Caprice
Latin America (Front)

2008: Pontiac G8 (Front)




Plate: D1351-O Gunn Metal





Plate: D1351-I Gunn Metal



Shim: A-5260-CL Anstro Mfg.



Shim: A-5261-CLVT Anstro Mfg.



Caliper Hardware (Abutment Clip)

Anstro Part Number: A-8330-S, (24192)
(IBI Part Number)



Sensor: A-516-S
Anstro Mfg.

Visit our Web Sites <http://www.anstroinc.com>
<http://www.ibilima.com>

Some Original Equipment parts shown for reference. Aftermarket product designs may vary.