

# Hydraulic Brake Group

Anstro Mfg Inc.

# Bulletin

Call For Sales/Customer Service

Bulletin Number 180  
Jan 12, 2009

Anstro Mfg: 203-879-1423  
Gunn Metal: 519-836-6672  
International Brake: 419-993-8140

**FMSI No. : D1398 (8506)**

**Application:**  
2009: Hyundai Elantra-Rear




Plate: D1398-O Gunn Metal






Plate: D1398-I Gunn Metal



Shim: A-5059-CL Anstro Mfg.



Shim: A-5019-CLVT Anstro Mfg.



Caliper Abutment Clip:  
IBI P/N 23740



Sensor: A-504-S  
Anstro Mfg.

Visit our Web Sites: <http://www.anstroinc.com>  
<http://www.ibilima.com>

*Some Original Equipment parts shown for reference. Anstro aftermarket product designs may vary.*