

Hydraulic Brake Group

Anstro Mfg Inc.

Bulletin

Call For Sales/Customer Service

Bulletin Number 184
Jan 18, 2009

Anstro Mfg: 203-879-1423
Gunn Metal: 519-836-6672
International Brake: 419-993-8140

FMSI No. :D1401 (8509)

Application:

2009: Toyota Venza-Front




Plate: D1401-O Gunn Metal




Plate: D1401-IL Gunn Metal



Plate: D1401-IR Gunn Metal



Sensor: P/N A-427-S
Anstro Mfg.



Shim: P/N A-5231-CLVT
Inner & Outer
Anstro Mfg.



Hardware:
Pad Spreader Spring
IBI P/N 24271



Caliper Hardware:
Abutment Clip
Anstro Mfg. P/N A-8338-S
IBI P/N 24269

Visit our Web Sites <http://www.anstroinc.com>
<http://www.ibilima.com>

Some Original Equipment parts shown for reference. Anstro aftermarket product designs may vary.