

# Hydraulic Brake Group

Anstro Mfg Inc.

# Bulletin

Call For Sales/Customer Service

Bulletin Number 185  
Jan 19, 2009

Anstro Mfg: 203-879-1423  
Gunn Metal: 519-836-6672  
International Brake: 419-993-8140


**FMSI No. :D1402 (8510)**

**Application:**

2009: Toyota Venza-Rear



Plate: D1402-O Gunn Metal



Shim: A-5257-CLVT Anstro Mfg.




Plate: D1402-I Gunn Metal



Sensor: P/N A-427-S  
Anstro Mfg.



Caliper Hardware:  
Abutment Clip  
Anstro Mfg. P/N A-8335-S  
IBI P/N 24268

Visit our Web Sites <http://www.anstroinc.com>  
<http://www.ibilima.com>

*Some Original Equipment parts shown for reference. Anstro aftermarket product designs may vary.*