

# Hydraulic Brake Group

Anstro Mfg Inc.

# Bulletin

Call For Sales/Customer Service

Bulletin Number 195  
Mar 10, 2009

Anstro Mfg: 203-879-1423  
Gunn Metal: 519-836-6672  
International Brake: 419-993-8140

**FMSI No. :D1408 (8516)**

**Application:**


2008-07 Hyundai Tiburon (Front)




Plate: D1408-Inner  
Gunn Metal



Plate: D1408-Outer  
Gunn Metal



Shim: A-5413-CLVT Inner & Outer  
Anstro Mfg.



Shim: A-4952-CL Inner & Outer  
Anstro Mfg.



Sensor: J-422-S Anstro Mfg.



Caliper Hardware:  
Abutment Clip  
IBI P/N 23501

Visit our Web Sites <http://www.anstroinc.com>  
<http://www.ibilima.com>

*Some Original Equipment parts shown for reference. Anstro aftermarket product designs may vary.*